




Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number K51007246846		2. Page 1 of 1		3. Emergency Response Phone (800) 485-3710		4. Manifest Tracking Number <b>008037714 FLE</b>					
5. Generator's Name and Mailing Address 2549 North New York Street Wichita, KS 67219 (316) 269-7400						Generator's Site Address (if different than mailing address) SAME							
6. Transporter 1 Company Name Clean Harbors						U.S. EPA ID Number MA0039322250							
7. Transporter 2 Company Name						U.S. EPA ID Number							
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 68145 (308) 235-4012						U.S. EPA ID Number NE0981723513							
Facility's Phone:													
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))					10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes			
						No.	Type						
	x	1. HAZARDOUS WASTE, SOLID, N.O.S., (POISON, LEAD), 9, PG III					1	CM	EST 12	Y	D004	D005	D007
		2.									D008	D039	D046
		3.											
	4.												
14. Special Handling Instructions and Additional Information 1. CR871506X01 EAC8171 TCH# CRT# 27091													
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.													
Generator's/Offeror's Printed/Typed Name Jim Tyson					Signature Jim Tyson			Month Day Year 2 5 15					
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:													
17. Transporter Acknowledgment of Receipt of Materials													
Transporter 1 Printed/Typed Name ROBIN G FIGLEY					Signature Rob Figley			Month Day Year 2 5 15					
Transporter 2 Printed/Typed Name					Signature			Month Day Year					
18. Discrepancy													
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection													
18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number													
Facility's Phone:													
18c. Signature of Alternate Facility (or Generator) Month Day Year													
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)													
1. H040		2.		3.		4.							
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a													
Printed/Typed Name					Signature			Month Day Year					

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>KSD007246846</b>	2. Page 1 of <b>1</b>	3. Emergency Response Phone <b>(800) 483-3718</b>	4. Manifest Tracking Number <b>008037714 FLE</b>		
5. Generator's Name and Mailing Address <b>Clean Harbors Kansas LLC</b> <b>2549 North New York Street</b> <b>Wichita, KS 67219</b> <b>(316) 269-7400</b>				Generator's Site Address (if different than mailing address) <b>SAME</b>			
6. Transporter 1 Company Name <b>clean Harbors</b>				U.S. EPA ID Number <b>MA0039322250</b>			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address <b>Clean Harbors Env Services Inc</b> <b>2247 South Highway 71</b> <b>Kimball, NE 69145</b> Facility's Phone: <b>(308) 235-4012</b>				U.S. EPA ID Number <b>NE0981723513</b>			
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	<b>x</b>	<b>1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III</b>	<b>1</b>	<b>CM</b>	<b>EST 12</b>	<b>y</b>	<b>D004 D005 D007</b> <b>D008 D039 D040</b>
14. Special Handling Instructions and Additional Information <b>1. CH831506X0B</b> <b>ERG#171</b>				<b>TRUCK # 1656</b> <b>CHRT # 27091</b>			
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name <b>Jim Tyson</b>				Signature 		Month Day Year <b>2/5/15</b>	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name <b>ROBIN GEIGLEY</b>				Signature 		Month Day Year <b>2/5/15</b>
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name				Signature		Month Day Year
	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	18b. Alternate Facility (or Generator)				Manifest Reference Number: _____ U.S. EPA ID Number _____		
	Facility's Phone: _____				18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____		
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. <b>H040</b>		2. _____		3. _____		4. _____	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name <b>Thomas Clark</b>				Signature 		Month Day Year <b>02/06/15</b>	

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>KSD007246846</b>		2. Page 1 of <b>1</b>		3. Emergency Response Phone <b>(800) 483-3718</b>		4. Manifest Tracking Number <b>008037714 FLE</b>							
5. Generator's Name and Mailing Address <b>Clean Harbors Env Servs LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400</b>						Generator's Site Address (if different than mailing address) <b>SAME</b>									
6. Transporter 1 Company Name <b>Clean Harbors</b>						U.S. EPA ID Number <b>MA0039322250</b>									
7. Transporter 2 Company Name						U.S. EPA ID Number									
8. Designated Facility Name and Site Address <b>Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 69145 (308) 235-4012</b>						U.S. EPA ID Number <b>NE0981723513</b>									
9a. HM						9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity		12. Unit Wt./Vol.		13. Waste Codes	
x		1. <b>HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (POLYURETHANE, LEAD), 9, PG III</b>				1		CM		EST 12		y		D004 D005 D007 D008 D039 D040	
		2.													
		3.													
		4.													
14. Special Handling Instructions and Additional Information <b>1. CH831506X05 ERG#171</b>										TRUCK # <b>1656</b> CHRT # <b>27091</b>					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.															
Generator's/Offor's Printed/Typed Name <b>Jim Tyson</b>										Signature <i>Jim Tyson</i>		Month Day Year <b>2 5 15</b>			
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.										Port of entry/exit: Date leaving U.S.:					
17. Transporter Acknowledgment of Receipt of Materials															
Transporter 1 Printed/Typed Name <b>KOBIN GEIGLEY</b>										Signature <i>Rob Geigley</i>		Month Day Year <b>2 5 15</b>			
Transporter 2 Printed/Typed Name										Signature		Month Day Year			
18. Discrepancy															
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection															
18b. Alternate Facility (or Generator)										Manifest Reference Number: U.S. EPA ID Number:					
Facility's Phone:															
18c. Signature of Alternate Facility (or Generator)										Signature		Month Day Year			
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)															
1. <b>H040</b>		2.		3.		4.									
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a															
Printed/Typed Name <b>Thomas Clark</b>										Signature <i>Thomas Clark</i>		Month Day Year <b>02 06 15</b>			



2247 South Highway 71  
Kimball, NE 69145

TEL 308-235-4012  
FAX 308-235-4307  
www.cleanharbors.com

DATE: 2/6/2015

MANIFEST: 008037714FLE

Dear Valued Customer:

In accordance with 40 CFR 264.12(b), Clean Harbors Environmental Services, Inc., Kimball Facility, has appropriate state and federal permits to accept, store, and/or treat the waste you shipped to our facility. This letter should be kept on file with your copy of the signed manifest.

Clean Harbors Environmental Services, Inc. makes every effort to ensure that signed copies of manifests are returned to the waste generator as quickly as possible following receipt of your waste at our facility. This allows us to provide you with rapid verification that your waste shipment arrived safely at our waste management facility.

Once your waste has been received, Clean Harbors' personnel will verify that the quantity that has been received matches the quantity that was shipped. We also inspect the material and conduct testing to ensure that it meets the facility's waste acceptance criteria as described in our Waste Analysis Plan, as well as processing requirements. Every effort is made to complete the waste verification as quickly as possible; however, it is possible that the signed copy of the manifest may be returned to you before the waste verification process is completed. If a significant discrepancy, as defined by US EPA regulations (40 CFR 264.72), is discovered during the waste verification process, we will contact you in order to reconcile the discrepancy. Additionally, we will work with you to make any corrections to the waste manifest that are necessary.

Sincerely,

Receiving Department